









Interpretation of weekly turbidity monitoring results, released 14 January 2009

- The data shows that all monitoring results were below the environmental limits and response levels
- A slight elevation in observed turbidity on 5 January 2009 at Mud Islands was due to biofouling of the sensor. The buoy was replaced and the readings returned to normal background levels. No dredging had occurred in South Channel during this period.