

First Quarter Notifications – 2009

The Office regularly receives notifications on the implementation of the Environmental Management Plan. Relevant notifications during the period from 1 March to 31 May 2009 are listed in the table below.

| Quarter 1, 2009: 1 March to 31 May 2009 | | |
|---|---|---|
| Date | Notification | Comment |
| 30/05/2009 | Pollution event – oil spill | Notification provided as required by EMP Table 6 that a spill of approximately 2 litres of diesel occurred in the South Channel on 30 May. |
| 27/05/2009 | Placement of contaminated material in bund | Notification provided as required by EMP Table 6 |
| 22/05/2009 | Post-construction plateau inspection towed video survey | Notification provided as required by EMP Table 6 |
| 21/05/2009 | Pollution event – oil spill | Notification provided that an oily substance was detected on the surface of the Yarra River near Yarraville as required by EMP Table 6. It was unrelated to the dredger, or support vessels, in the area. |
| 14/05/2009 | Baywide monitoring - algal bloom | Notification provided as required by EMP Table 6 |
| 08/05/2009 | Project Delivery Standard | Minor non-conformance with Project Delivery Standard 24 on 19 April 2009 for dredging outside of the 65m zone along the edge of the construction zone in South Channel, near Hovell Pile. |
| 06/05/2009 | Dredging schedule | Notification (Rev 2 Update 4) provided as required by EMP Table 6 |
| 05/05/2009 | Post-construction deep reef habitat survey | Notification provided as required by EMP Table 6 |
| 29/04/2009 | Completion of dredging of contaminated sediments within an area (Yarra River near services) | Notification provided as required by EMP Table 6 |

| | | |
|------------|--|--|
| 26/04/2009 | Environmental limit exceeded | Notification that turbidity environmental limit exceeded, as required by EMP Table 6 |
| 15/04/2009 | Placement of contaminated material in bund | Notification provided as required by EMP Table 6 |
| 09/04/2009 | Dredging schedule | Notification (Rev 2 Update 3) provided as required by EMP Table 6 |
| 09/04/2009 | Baywide monitoring - algal bloom | Notification provided as required by EMP Table 6 |
| 09/04/2009 | Baywide monitoring - algal bloom | Notification provided as required by EMP Table 6 |
| 09/04/2009 | Audit of PoMC implementation of the EMP by external auditor (Audit of the mechanisms used to monitor environmental performance – March 2009) | Notification provided as required by EMP Table 6 |
| 02/04/2009 | Pollution event – oil spill | Notification provided as required by EMP Table 6 that a spill of approximately 5-10 litres of Panolin (a biodegradable hydraulic fluid) had occurred in Port Melbourne Channel on 1 April. |
| 20/03/2009 | Completion of dredging of contaminated sediments within an area (Yarra River near services) | Notification provided as required by EMP Table 6 |
| 17/03/2009 | Audit of PoMC implementation of the EMP by external auditor (Targeted audit of EMP requirements for Management of Contaminated Sediments – March 2009) | Notification provided as required by EMP Table 6 |
| 10/03/2009 | Quarterly project report | Quarterly Project Report No. 4 provided as required by EMP Table 6 |
| 05/03/2009 | Dredging schedule | Notification (Rev 2 Update 2) provided as required by EMP Table 6 |
| 05/03/2009 | Response Level reached | Notification that turbidity Response Level 2 reached as required by EMP Table 6 |

| | | |
|------------|----------------------------------|--|
| 05/03/2009 | Baywide monitoring - algal bloom | Notification provided as required by EMP Table 6 |
|------------|----------------------------------|--|