









Interpretation of weekly turbidity monitoring results, released 11 March 2009

- Despite some noticeable undulations in the south of the bay during periods of dredging, levels remained low across all sites with the following exception:
- Due to strong winds, as a precautionary measure the *Prins* stopped working at about 3pm on Wednesday 4 March. During the ensuing period of no dredging, two response level 2 readings were recorded at monitoring site SE DMG - at 6pm and at midnight. Turbidity levels declined during the night and the *Prins* resumed dredging at about 6.30am on Thursday 5 March. No other conformance sites in the bay recorded turbidity levels above their respective response levels.