

## Second Quarter 2009 Notifications

The Office regularly receives notifications on the implementation of the Environmental Management Plan. Relevant notifications during the period from 1 June to 31 August 2009 are listed in the table below.

Quarter 2, 2009: 1 June 2009 to 31 August 2009		
Date	Notification	Comment
31/08/2009	Dredging Schedule	Notification (Rev 2 Update 9) provided as required by EMP Table 6.
27/08/2009	Baywide monitoring - algal bloom.	Notification provided as required by EMP Table 6.
20/08/2009	Completion of dredging of contaminated sediments within an area (32 South Wharf)	Notification provided as required by EMP Table 6
19/08/2009	Audit of PoMC implementation of the EMP by external auditor (Targeted audit of EMP requirements for sand capping – August 2009)	Notification provided as required by EMP Table 6
16/08/2009	Response level reached	Notification that turbidity response level 2 reached as required by EMP Table 6.
14/08/2009	Completion of dredging of contaminated sediments within an area (Yarraville)	Notification provided as required by EMP Table 6
05/08/2009	Audit of PoMC implementation of the EMP by external auditor (Targeted audit of EMP requirements for construction of the bund – August 2009)	Notification provided as required by EMP Table 6
05/08/2009	Dredging Schedule	Notification (Rev 2 Update 8) provided as required by EMP Table 6.
04/08/2009	Project Delivery Standard	Minor non-conformance with Project Delivery Standard 34 on 3 August 2009 for disposal of uncontaminated clay outside of the PoM Dredge Material Ground.
03/08/2009	Response level reached	Notification that turbidity response level 1 reached as required by EMP Table 6.
31/07/2009	Baywide monitoring - algal bloom.	Notification provided as required by EMP Table 6.
19/07/2009	Response level reached	Notification that turbidity response level 2 reached as required by EMP Table 6.
17/07/2009	Dredging Schedule	Notification (Rev 2 Update 7) provided as required by EMP Table 6.
08/07/2009	Dredging Schedule	Notification (Rev 2 Update 6) provided as required by EMP Table 6.
06/07/2009	Baywide monitoring - algal bloom.	Notification provided as required by EMP Table 6.

03/07/2009	Audit of PoMC implementation of the EMP by external auditor (Focused audit of dredging in the South Channel & mechanisms to protect seagrass – June 2009)	Notification provided as required by EMP Table 6
03/07/2009	Pollution event – oil spill	Notification provided as required by EMP Table 6 that a spill of 50-100 litres of hydraulic fluid had occurred on 2 July. Over 95% was recovered on board the dredge with only approximately 2 litres entering the Yarra River.
19/06/2009	Post-construction Bathymetric Survey (3 month) of the Entrance	Notification provided as required by EMP Table 6
17/06/2009	Completion of dredging of contaminated sediments within an area (Gellibrand Pier Dolphin and Beacon 38B)	Notification provided as required by EMP Table 6
13/06/2009	Pollution event – oil spill	Notification provided as required by EMP Table 6 that a spill of approximately 100 litres of Panolin (a biodegradable hydraulic fluid) had occurred on 12 June. Some 80 to 90% was recovered on board the dredge and an estimated 10 to 20 litres entered the Yarra River.
12/06/2009	Loss of one 6 hour EWMA for a turbidity conformance location	Notification provided as required by EMP Table 6.
11/06/2009	Baywide monitoring - algal bloom.	Notification provided as required by EMP Table 6.
10/06/2009	Response level reached	Notification that turbidity response level 1 reached as required by EMP Table 6.
09/06/2009	Quarterly project report	Quarterly Project Report No. 5 provided as required by EMP Table 6.
05/06/2009	Placement of contaminated material in bund	Notification provided as required by EMP Table 6
03/206/2009	Dredging Schedule	Notification (Rev 2 Update 5) provided as required by EMP Table 6.
02/06/2009	Pollution event – oil spill	Notification provided as required by EMP Table 6 that a spill of approximately 50 litres of Panolin (a biodegradable hydraulic fluid) had occurred in the Yarra River on 2 June.
01/06/2009	Pollution event – oil spill	Notification provided as required by EMP Table 6 that a spill of approximately 5-6 litres of Panolin (a biodegradable hydraulic fluid) had occurred in the Yarra River on 31 May.